

Certificate of Structural Repair

PRC Repair Specification:

[2014,BSF,Reema,01]

Requirements for repair of Reema House Type

Certificate No. [PRC - 00009]

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**144 Byron Road
Southampton
SO19 6EY**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014,BSF,Reema,01 in respect of the repair of Reema House Type, do certify that the repair was carried out in accordance with PRC Repair Specification 2014,BSF,Reema,01: "Requirements for repair of Reema House Type".

[10 June 2016]

Contract Completion Date

[0009]

Contract Number

[Mr Alan Cairns]

Name, Position

Signature

[Alan Cairns Associates Ltd]

Registered Practitioner Company Name

[20 September 2016]

Issue date



PRC Repair Specification: 2014,BSF,Reema,01
 Repair
 Certificate No. PRC - 00009

Certificate of Structural

Schedule Continued:

Contract premises:

0009

144 Byron Road
Southampton
SO19 6EY

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014,BSF,Reema,01, against which the repair was undertaken.	[]

Works not completed or excluded	Location
[]	[]

Notes:

[N/A]

Mr Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

20 September 2016

Issue date

