

## Certificate of Structural Repair

### PRC Repair Specification:

[2014,BSF,Reema,01]

Requirements for repair of Reema House Type

Certificate No. [PRC - 00010]

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**23 Scotland Close  
Fair Oak  
Eastleigh  
SO50 7BQ**



## Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014,BSF,Reema,01 in respect of the repair of Reema House Type, do certify that the repair was carried out in accordance with PRC Repair Specification 2014,BSF,Reema,01: "Requirements for repair of Reema House Type".

[20 August 2016]

Contract Completion Date

[0010]

Contract Number

[Mr Alan Cairns]

Name, Position

Signature

[Alan Cairns Associates Ltd]

Registered Practitioner Company Name

[15 September 2016]

Issue date



PRC Repair Specification: 2014,BSF,Reema,01  
 Repair  
 Certificate No. PRC - 00010

Certificate of Structural

Schedule Continued:

Contract premises: 0010  
 Contract Number  
**23 Scotland Close**  
**Fair Oak**  
**Eastleigh**  
**SO50 7BQ**

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014,BSF,Reema,01, against which the repair was undertaken.	

Works not completed or excluded	Location

**Notes:**

[N/A ]

Mr Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

15 September 2016

Issue date

