

Certificate of Structural Repair

PRC Repair Specification:
2014, BSF, Reema, 01

Requirements for repair of Reema House Type1

Certificate No. PRC - 0018

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**3 Birch Road
Tadley
Hampshire
RG26 4QT**



Schedule

Alan Cairns Associates Ltd.

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014, BSF, Reema, 01 in respect of the repair of House Type1, do certify that the repair was carried out in accordance with PRC Repair Specification 2014, BSF, Reema, 01: "Requirements for repair of House Type1".

25 July 2018

Contract Completion Date

0018

Contract Number

Mr Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd.

Registered Practitioner Company Name

22 May 2019

Issue date



PRC Repair Specification:
2014, BSF, Reema, 01
Certificate No. PRC - 0018

Certificate of Structural Repair

Schedule Continued:

Contract premises:

**3 Birch Road
Tadley
Hampshire
RG26 4QT**

0018

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014, BSF, Reema, 01, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

N/A

Mr Alan Cairns

Name, Position



Signature

Alan Cairns Associates Ltd.

Registered Practitioner Company Name

22 May 2019

Issue date

