

Certificate of Structural Repair

PRC Repair Specification:
2017:BSF,Airey, 01

Requirements for repair of Airey House

Certificate No. PRC - 0059

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**24 Park View
Royston
SG8 5PS**



Schedule

Brian Stocker

1) Issuing Practitioner

PRC-0001

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2017:BSF,Airey, 01 in respect of the repair of Airey House , do certify that the repair was carried out in accordance with PRC Repair Specification 2017:BSF,Airey, 01: "Requirements for repair of Airey House".

18 February 2019


Contract Completion Date

0059

Contract Number

Brian Stocker

Name, Position



Signature

Brian Stocker

Registered Practitioner Company Name

01 July 2019

Issue date



PRC Repair Specification:
2017:BSF,Airey, 01

Certificate No. PRC - 0059

Schedule Continued:

Certificate of Structural Repair

Contract premises:

24 Park View
Royston
SG8 5PS

0059

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2017:BSF,Airey, 01, against which the repair was undertaken.	


Works not completed or excluded	Location

Notes:

Click here to enter text.

Brian Stocker

Name, Position



Signature

Brian Stocker

Registered Practitioner Company Name

01 July 2019

Issue date

