

## Certificate of Structural Repair

PRC Repair Specification:  
2014:BSF,Reema, 01

Requirements for repair of Reema House

**Certificate No. PRC - 0080**

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**17 Burnham Road  
Tadley  
RG26 4QN**



## Schedule

Brian Stocker

1) Issuing Practitioner

PRC-0001

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF,Reema, 01 in respect of the repair of Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF,Reema, 01: "Requirements for repair of Reema House".

04 September 2019

Contract Completion Date

0080

Contract Number

Brian Stocker

Name, Position

Signature

Brian Stocker

Registered Practitioner Company Name

24 October 2019

Issue date



PRC Repair Specification:  
2014:BSF,Reema, 01  
Certificate No. PRC - 0080  
Schedule Continued:

Certificate of Structural Repair

Contract premises:  
**17 Burnham Road**  
**Tadley**  
**RG26 4QN**

**0080**  
Contract Number

| Scope of Works  | Location |
|---|----------|
| This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF,Reema, 01, against which the repair was undertaken. |          |


| Works not completed or excluded | Location |
|---------------------------------|----------|
|                                 |          |
|                                 |          |

**Notes:**

Click here to enter text.

Brian Stocker

Name, Position



Signature

Brian Stocker

Registered Practitioner Company Name

24 October 2019

Issue date

