

## Certificate of Structural Repair

PRC Repair Specification:  
**2014:BSF,Reema, 01**

Requirements for repair of House Type Reema

**Certificate No. PRC - 0091**

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**39 Ellwood Close  
Thornhill  
Southampton  
SO19 6BL**



## Schedule

Alan Cairns

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF,Reema, 01 in respect of the repair of House Type Reema , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF,Reema, 01: "Requirements for repair of House Type Reema".

20 July 2020

Contract Completion Date

0065

Contract Number

Alan Cairns

Name, Position



Signature

Alan Cairns

Registered Practitioner Company Name

05 August 2020

Issue date



PRC Repair Specification:  
2014:BSF,Reema, 01  
Certificate No. PRC - 0091  
Schedule Continued:

Certificate of Structural Repair

Contract premises:  
**39 Ellwood Close**  
**Thornhill**  
**Southampton**  
**SO19 6BL**

0065  
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF,Reema, 01, against which the repair was undertaken.	

Works not completed or excluded	Location
N/A	
N/A	

**Notes:**

[Click here to enter text.](#)

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

05 August 2020

Issue date

