

Certificate of Structural Repair

**PRC Repair Specification:
2014:BSF,Reema, 01**

Requirements for repair of Reema House

Certificate No. PRC - 0064

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**25 Windmill Piece,
Chiseldon,
Wiltshire,
SN4 0NY**



Schedule

Brian Stocker

1) Issuing Practitioner

PRC-0001

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF,Reema, 01 in respect of the repair of Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF,Reema, 01: "Requirements for repair of Reema House " .

22 April 2019

Contract Completion Date

0064

Contract Number

Brian Stocker

Name, Position

Signature

Brian Stocker

Registered Practitioner Company Name

09 July 2019

Issue date



PRC Repair Specification:
2014:BSF,Reema, 01
Certificate No. PRC - 0064
Schedule Continued:

Certificate of Structural Repair

Contract premises:
**25 Windmill Piece,
Chiseldon,
Wiltshire,
SN4 0NY**


0064
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF,Reema, 01, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:
Click here to enter text.

Brian Stocker
Name, Position



Signature

Brian Stocker
Registered Practitioner Company Name

09 July 2019
Issue date

