

Certificate of Structural Repair

**PRC Repair Specification:
2014:BSF,Reema, 01**

Requirements for repair of Reema House

Certificate No. PRC - 0071

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**107 Burke Drive
Thornhill
Southampton
SO19 6EG**



Schedule

Brian Stocker

1) Issuing Practitioner

PRC-0001

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF,Reema, 01 in respect of the repair of Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF,Reema, 01: "Requirements for repair of Reema House " .

15 June 2019

Contract Completion Date

0071

Contract Number

Brian Stocker

Name, Position

Signature

Brian Stocker

Registered Practitioner Company Name

06 August 2019

Issue date



PRC Repair Specification:
2014:BSF,Reema, 01
Certificate No. PRC - 0071
Schedule Continued:

Certificate of Structural Repair

Contract premises:

107 Burke Drive
Thornhill
Southampton
SO19 6EG

0071

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF,Reema, 01, against which the repair was undertaken.	


Works not completed or excluded	Location

Notes:

Click here to enter text.

Brian Stocker

Name, Position



Signature

Brian Stocker

Registered Practitioner Company Name

06 August 2019

Issue date

