

Certificate of Structural Repair

**PRC Repair Specification:
2017:BSF,Airey, 01**

Requirements for repair of Airey House

Certificate No. PRC – 055

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**100 Walsh Avenue
Bristol
BS14 9SH**



Schedule

Alan Cairns

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2017:BSF,Airey, 01 in respect of the repair of Airey House , do certify that the repair was carried out in accordance with PRC Repair Specification 2017:BSF,Airey, 01: “Requirements for repair of Airey House ”.

22 June 2018

Contract Completion Date

0055

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

27 November 2019

Issue date



PRC Repair Specification:
2017:BSF,Airey, 01
Certificate No. PRC – 055
Schedule Continued:

Certificate of Structural Repair

Contract premises:
100 Walsh Avenue
Bristol
BS14 9SH

0055
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2017:BSF,Airey, 01, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:
 Click here to enter text.

Alan Cairns
Name, Position



Signature

Alan Cairns
Registered Practitioner Company Name

27 November 2019
Issue date

